

# ALERT BULLETIN

AB 2026:6/2-2

2/19/2026

2317651

TO: Boeing Commercial Airplane Company

INFO: FAA (AVP-1, AVP-200, AFS-200, AFS-900, AFS-260, AFS-100, AIR-720, AIR-780, AIR-360, SEA-AEG), A4A, ALPA, AMFA, ASAP, ATSG, CAPA, IAM, IBT, ICAO, ICASS, IFALPA, IPA, NTSB, PAMA, RAA, SWAPA, TWU

FROM: Becky L. Hooley, Director  
NASA Aviation Safety Reporting System

SUBJ: B737 MAX 8 Exhaust Plume Issue

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the following:

ASRS received a report from a B737 MAX 8 pilot describing an issue with an exhaust plume. Reporter stated that shortly before departure they were advised by a ramp employee that the #1 engine had a large crack in the exhaust plume. The ramp employee stated that he had seen similar damage in the recent past, and the reporter mentioned that another pilot had seen similar damage on a different aircraft.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooley at (408) 541-2854 or email at [becky.l.hooley@nasa.gov](mailto:becky.l.hooley@nasa.gov).



Aviation Safety Reporting System  
P.O. Box 189 | Moffett Field, CA | 94035-0189



## ACN 2317651

### DATE / TIME

Date of Occurrence 202512  
Local Time Of Day 0001 to 0600

### PLACE

Locale ZZZ.Airport  
State US  
Altitude - AGL 0

### AIRCRAFT / EQUIPMENT X

ATC / Advisory - Ramp ZZZ  
Make Model Name B737 MAX 8  
Operating Under FAR Part 121

### COMPONENT 1

Aircraft Component Turbine Engine

### PERSON 1

Function - Flight Crew Captain  
Function - Flight Crew Pilot Flying  
ASRS Report Number 2317651

### EVENTS

Anomaly Aircraft Equipment Problem - Critical  
Anomaly Deviation / Discrepancy - Procedural - Published  
Material / Policy  
Anomaly Ground Event / Encounter - Other / Unknown  
Detector - Person Flight Crew  
Detector - Person Ground Personnel  
Result - General Flight Cancelled / Delayed  
Result - General Maintenance Action  
Result - Aircraft Aircraft Damaged

### NARRATIVE 1

While readying to close forward entry door, ramper motioned for my attention to take a look at the #1 engine. 737 MAX.

FO and I went downstairs and saw the exhaust plume metal had a large and visible crack. Contacted Maintenance, wrote up and flight was delayed to next day. Ramper said he had found one a week or two ago – this was the second. It is above the tailpipe and would require crouching by the person doing the walkaround – the FO and I are unaware of guidance or training to inspect specifically this area.

Due to long duty, I was released and was returning to ZZZ via jumpseat. When I arrived at jumpseat, Captain said the exact same situation had just occurred to him. His aircraft was now out of service until the next day.

Cause: Inspection and review fleetwide. Was this just happenstance or is there something that we are not viewing correctly on walkarounds.

If heat is allowed to penetrate crack into pylon, does this introduce the kind of risk that would be expected?  
Fuel, HYD, fire, structural mount failure?

---

## **SYNOPSIS**

B737 MAX 8 pilot reported a ramp employee showed the flight crew the exhaust plume metal had a large and visible crack, and mentioned that this was the second time noticing this issue. When the reporter later returned as a jumpseater on another aircraft, the same problem occurred again.