

1/27/2023

FOR YOUR INFORMATION

2023-16/11-5

1949549

To: Jeppesen Sanderson Inc., FAA (AFS-400, DFW IFO), Airport Manager,
Queretaro Intercontinental Airport (MMQT) Queretaro, Mexico

Info: FAA (AVP-1, AVP-200, AFS-260, AFS-200), A4A, ALPA, AOPA, APA, ASAP, ATSG,
CAPA, ICASS, ICAO, IFALPA, NBAA, NTSB

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: MMQT Airport Diagram Out of Date

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 1949549

DATE / TIME

Date of Occurrence 202211
Local Time Of Day 0601 to 1200

PLACE

Locale MMQT.Airport
State FO
Altitude - AGL 0

ENVIRONMENT

Flight Conditions VMC

AIRCRAFT / EQUIPMENT X

Make Model Name Commercial Fixed Wing
Operating Under FAR Part 121

COMPONENT 1

Aircraft Component Navigation Database

PERSON 1

Function - Flight Crew Captain
Function - Flight Crew Pilot Flying
ASRS Report Number 1949549

EVENTS

Anomaly Deviation / Discrepancy - Procedural - Published
Material / Policy
Anomaly Ground Event / Encounter - Other / Unknown
Detector - Person Flight Crew
Result - General None Reported / Taken

NARRATIVE 1

MMQT 10-9 airport diagram is not up to date. There are additional taxiways that are open and useable not depicted on the diagram. Also, they use a Ground Control frequency that is not depicted.

SYNOPSIS

Air Carrier Captain reported the airport chart for MMQT should be updated.