

4/6/2023

FOR YOUR INFORMATION

2023-51/11-9

1978157

To: Jeppesen Sanderson Inc, Airport Manager, Amsterdam Airport Schiphol (EHAM), Netherlands

Info: FAA (AVP-1, AVP-200, AFS-260, ANG-1, AFS-200), A4A, ALPA, AOPA, APA, ASAP, ATSG, CAPA, ICAO, ICASS, IFALPA, NAFI, NBAA, NTSB

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: FD Pro X EHAM Runway Data Error

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 1978157

DATE / TIME

Date of Occurrence	202302
Local Time Of Day	No Local Time Of Day Stated

PLACE

Locale	EHAM.Airport
State	FO
Altitude - AGL	0

AIRCRAFT / EQUIPMENT X

Make Model Name	No Aircraft
Operating Under FAR Part	121

COMPONENT 1

Aircraft Component	Navigation Database
--------------------	---------------------

PERSON 1

Function - Flight Crew	First Officer
ASRS Report Number	1978157

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Flight Crew
Result - Flight Crew	Overcame Equipment Problem

NARRATIVE 1

FD ProX Version 4.6.1 EHAM Runway data issue. FD Pro X Version 4.6.1 EHAM/AMS Airport runway data is incorrect for runways 4/22 and 18R/36L. Moreover the runway lengths are swapped. Select INFO/WX button on left, scroll down to Runways, note distance for 4/22 is 12,467 ft. incorrectly, and 18R/36L is 6,627 ft. incorrect. When each runway is selected for more detail, the proper distance is noted.

SYNOPSIS

Air carrier pilot reported runway data for the EHAM airport on the FD Pro X Version 4.6.1 is incorrect.