## 1/27/2025

## FOR YOUR INFORMATION

2025-16/10-3

2194544

To: FAA (AJV-A, ATM SCT TRACON)

Info: FAA (AVP-1, AVP-200, AFS-200, AFS-260, AWP-600, Director of Air Traffic Operations

WSA), A4A, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, IBT, ICAO, ICASS,

IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director

NASA Aviation Safety Reporting System

Re: Similar Sounding Fix Names - OROSZ/COREZ

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.





ACN 2194544	
DATE / TIME	
Date of Occurrence Local Time Of Day	202412 1801 to 2400
PLACE	
Locale State Altitude - MSL	SCT.TRACON CA 20000
ENVIRONMENT	
Weather Weather	Icing Turbulence
AIRCRAFT / EQUIPMENT X	
ATC / Advisory - Center  Make Model Name  Operating Under FAR Part	ZLA Medium Transport, Low Wing, 2 Turbojet Eng 91
PERSON 1	
Function - Flight Crew ASRS Report Number	Captain 2194544
EVENTS	
Anomaly Anomaly Anomaly	Deviation - Track / Heading - All Types  Deviation / Discrepancy - Procedural - Clearance  Deviation / Discrepancy - Procedural - Published  Material / Policy
Detector - Person Result - Flight Crew	Air Traffic Control Returned To Clearance
NARRATIVE 1	

While departing SNA on the HHERO3 departure, we were cleared the OROSZ transition, COREZ, as filed. While imputing our departure into the FMS both myself and the other crew member failed to realize that OROSZ transition was unselected and we were missing several fixes between HHERO and COREZ placing us on a direct path from HHERO to COREZ. It is my belief that the similarity in the pronunciation of these fixes that led to our imputing error. Additionally we have implemented a policy where the flight crew must review every flight plan fix together and not separately to avoid making a similar mistake. As this could affect flight crews in the future I believe consideration should be given to these fixes and how the similar names may cause confusion to flight crews in the future.

## **SYNOPSIS**

Captain reported similar sounding fix names for a departure procedure and its transition, which resulted in improper loading of the navigation system and the aircraft proceeding to an incorrect fix.