3/20/2025 **F**

FOR YOUR INFORMATION

2025-65/5-19

2211901

To: Airport Manager, Gustavo Diaz Ordaz International Airport (MMPR), Mexico,

FAA (DFW IFO), Jeppesen Sanderson Inc.

Info: FAA (AFS-260, AFS-200, AVP-1, AVP-200), A4A, AOPA, ASAP, ICASS, ICAO,

IFALPA, NBAA, NTSB, RAA, Federal Civil Aviation Agency (AFAC, Mexico)

From: Becky L. Hooey, Director

NASA Aviation Safety Reporting System

Re: MMPR Ramp Charting

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.





ACN 2211901	
DATE / TIME	
Date of Occurrence Local Time Of Day	202502 0601 to 1200
PLACE	
Locale State Altitude - AGL	MMPR.Airport FO 0
AIRCRAFT / EQUIPMENT X	
ATC / Advisory - Ground Make Model Name Operating Under FAR Part	MMPR Commercial Fixed Wing 121
PERSON 1	
Function - Flight Crew ASRS Report Number	Pilot Flying 2211901
EVENTS	
Anomaly Davis	Deviation / Discrepancy - Procedural - Published Material / Policy
NARRATIVE 1	Flight Crew

Taxi in from landing to Gate XX. Spots depicted on JEPPS are completely wrong. We almost taxied down alley beyond point of turning around. We were actually going to a hardstand (we were unaware) and did not see rampers positioned at a completely different location. The numbered spots at the airport DO NOT correlate to those on our JEPPS Page 10-9A for PVR (MMPR).

Cause: Incorrect information published on JEPPS. Correct diagram on Page 10-9A PVR to correspond with actual airport spot numbers.

SYNOPSIS

Air carrier pilot flying reported ramp location spots depicted on the Jeppesen airport diagram are different from the actual spot numbers at MMPR Airport.