

6/3/2025

**FOR YOUR INFORMATION**

2025-130/4-5

To: Airport Manager, Marshall Islands International Airport, (PKMJ), Majuro Atoll, 2232990  
Republic of the Marshall Islands


Info: FAA (LAX-IFO, AVP-1, AVP-200, AFS-200, AFS-260), A4A, ALPA, IFALPA, AMFA,  
ASAP, ATSG, ICAO, ICASS, IATA, IPA, NATA, NTSB, Republic of the Marshall Islands  
Ports Authority

From: Becky L. Hooey, Director  
NASA Aviation Safety Reporting System

Re: PKMJ/MAJ Wind Sock Issues

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at [becky.l.hooey@nasa.gov](mailto:becky.l.hooey@nasa.gov).



Aviation Safety Reporting System  
P.O. Box 189 | Moffett Field, CA | 94035-0189



**ACN 2232990****DATE / TIME**

Date of Occurrence	202504
Local Time Of Day	No Local Time Of Day Stated

**PLACE**

Locale	PKMJ.Airport
State	FO
Altitude - AGL	0

**ENVIRONMENT**

Flight Conditions	VMC
-------------------	-----

**AIRCRAFT / EQUIPMENT X**

Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

**PERSON 1**

Function - Flight Crew	Captain
ASRS Report Number	2232990

**EVENTS**

Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Anomaly Detector - Person	Ground Event / Encounter - Ground Equipment Issue Flight Crew

**NARRATIVE 1**

The MAJ windsock is tattered and over half the fabric is missing. The windsock light is also INOP. There is no NOTAM on the windsock.

**SYNOPSIS**

Air carrier Captain reported there is no NOTAM for the tattered windsock with the inoperative light at PKMJ Airport.