

10/27/2025

FOR YOUR INFORMATION

2025-258/5-87

To: Airport Manager, Denver Int'l Airport (DEN), CO, FAA (ANM-600)

2283049

Info: FAA (AAS-1, AJV-A, AVP-1, AVP-200, AFS-260, AFS-200, AAS-300, ATM DEN Tower Director of Air Traffic Operations WSA, Runway Safety Team), A4A, ALPA, AMFA, APA, ASAP, ATSG, CAPA, IAM, IATA, ICASS, IFALPA, IPA, NTSB, PAMA, SWAPA, TWU, Jeppesen Sanderson Inc.

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: DEN Taxiway Lighting

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2283049**DATE / TIME**

Date of Occurrence	202509
Local Time Of Day	No Local Time Of Day Stated

PLACE

Locale	DEN.Airport
State	CO
Altitude - AGL	0

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Ground	DEN
Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

PERSON 1

Function - Flight Crew	Captain
ASRS Report Number	2283049

EVENTS

Anomaly	Ground Event / Encounter - Other / Unknown
Detector - Person	Flight Crew

NARRATIVE 1

There are no centerline taxi lights on the transition from G to WA. It's a black hole and disorienting.

SYNOPSIS

Air carrier Captain reported there are no taxiway centerline lights from Taxiway G to WA at DEN.