

8/4/2026

FOR YOUR INFORMATION

2026-269/5-79

To: Airport Manager, Louisville Muhammad Ali International Airport (SDF), 2379610
KY, FAA (ASO-600)


Info: FAA (AVP-1, AVP-200, AAS-1, AFS-260, AFS-200, ATM SDF Tower, Director of Air
Traffic Operations ESA South), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSG, EAA,
ICAO, ICASS, IFALPA, NAFI, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: SDF Taxiway Signage

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2379610**DATE / TIME**

Date of Occurrence	202606
Local Time Of Day	1201 to 1800

PLACE

Locale	SDF.Airport
State	KY
Altitude - AGL	0

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Ground	SDF
Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

PERSON 1

Function - Flight Crew	Pilot Not Flying
ASRS Report Number	2379610

EVENTS

Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Anomaly	Ground Event / Encounter - Other / Unknown
Detector - Person	Flight Crew
Result - General	None Reported / Taken

NARRATIVE 1

The past several flights at SDF Ive noticed when northbound on taxiway C and crossing runway 29, there is not a directional taxiway sign identifying taxiway G for aircraft northbound on C. This is a common taxi route and could create confusion. I do not recall seeing a NOTAM for this either.

SYNOPSIS

Air carrier pilot reported possible confusion due to the lack of taxiway directional signage at SDF airport.