7/15/2024

FOR YOUR INFORMATION

2024-134/10-13

2125425

To: FAA (AJV-A, ATM ZLA ARTCC)

Info: FAA (AVP-1, AVP-200, AFS-200, AFS-260, AWP-600, Director of Air Traffic Operations

WSA), A4A, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, IBT, ICAO, ICASS,

IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director

NASA Aviation Safety Reporting System

Re: Similar Sounding Fix Names - CABAB/CEDAB

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.





ACN 2125425	
DATE / TIME	
Date of Occurrence Local Time Of Day	202405 No Local Time Of Day Stated
PLACE	,
Locale State	ZLA.ARTCC CA
AIRCRAFT / EQUIPMENT X	
ATC / Advisory - Center Make Model Name Operating Under FAR Part	ZLA Commercial Fixed Wing 121
PERSON 1	
Function - Flight Crew Function - Flight Crew ASRS Report Number	First Officer Pilot Flying 2125425
EVENTS	
Anomaly Anomaly Anomaly Result - Flight Crew Result - Flight Crew Result - Flight Crew Result - Air Traffic Control Result - Air Traffic Control	ATC Issue - All Types Deviation - Track / Heading - All Types Deviation / Discrepancy - Procedural - Clearance Became Reoriented Requested ATC Assistance / Clarification Returned To Clearance Issued New Clearance Provided Assistance
NARRATIVE 1	

In cruise we were given a few reroutes. The last reroute was, "Direct CABAB direct PRB flight plan route." We saw a similar sounding fix CEDAB on the arrival and headed that way. After a few minutes, ATC gave us a heading toward the direction they wanted us to go originally. We then continued on to SBP without issue.

SYNOPSIS

Air carrier First Officer reported being cleared for CABAB but the flight crew mistakenly proceeded direct to another fix that was similar, CEDAB.