

7/1/2026


FOR YOUR INFORMATION

2026-224/10-20

To: FAA (ATM MSY Tower, ATM MSY TRACON), Jeppesen Sanderson Inc. 2365464
Info: FAA (AAS-1, AAS-300, AVP-1, AVP-200, ASW-600, AFS-260, AFS-200, AJV-A, Runway Safety Team, Director of Air Traffic Operations CSA), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, ICASS, IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA, Airport Manager, Louis Armstrong New Orleans Int'l Airport (MSY), LA
From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System
Re: MSY ILS 29 FAF ZUTAT Does Not Load Properly

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2365464**DATE / TIME**

Date of Occurrence	202605
Local Time Of Day	No Local Time Of Day Stated

PLACE

Locale	MSY.Airport
State	LA

ENVIRONMENT

Flight Conditions	VMC
-------------------	-----

AIRCRAFT / EQUIPMENT X

ATC / Advisory - TRACON	MSY
Make Model Name	B737 Undifferentiated or Other Model
Operating Under FAR Part	121

COMPONENT 1

Aircraft Component	FMS/FMC
--------------------	---------

PERSON 1

Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying
ASRS Report Number	2365464

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Detector - Person	Flight Crew
Result - Flight Crew	Overcame Equipment Problem

NARRATIVE 1

ILS 29 MSY FAF ZUTAT does not load on legs page when ILS selected. It must be manually added to the legs.

SYNOPSIS

Air carrier Captain reported ILS 29 MSY FAF ZUTAT does not load on legs page when ILS selected.