

8/13/2026

FOR YOUR INFORMATION

2026-289/11-58

To: Jeppesen Sanderson Inc.

2383413


Info: FAA (AVP-1, AAS-1, AVP-200, AJV-A, AFS-260, ASO-600, AFS-200, AAS-300, Director of Air Traffic Operations ESA South), ATSG, ALPA, IFALPA, AOPA, APA, ASAP, A4A, ATSAP, CAPA, IATA, ICASS, IFALPA, NATCA, NBAA, NTSB, RAA, SWAPA, Airport Manager, Orlando Int'l Airport (MCO), FL.

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: MCO GTOUT1 STAR FD Pro NOTAM Anomaly

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2383413**DATE / TIME**

Date of Occurrence	202607
Local Time Of Day	1801 to 2400
Local Time Of Day	No Local Time Of Day Stated

PLACE

Altitude - AGL	0
----------------	---

ENVIRONMENT

Flight Conditions	VMC
-------------------	-----

AIRCRAFT / EQUIPMENT X

Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

PERSON 1

Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Not Flying
ASRS Report Number	2383413

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - Published
	Material / Policy
Detector - Person	Flight Crew
Result - General	None Reported / Taken

NARRATIVE 1

FliteDeck Pro filtering NOTAM it should not be filtering. It's GTOUT1 STAR into MCO. NICCK fix should come up crossing restriction missing 12,000 feet at 250 kt. Only comes up when all NOTAMs selected.

SYNOPSIS

Air carrier First Officer reported Jeppesen's FliteDeck Pro is filtering NOTAMs it should not be filtering and information is missing, depending on what is selected.