

3/2/2023

FOR YOUR INFORMATION

2023-32/5-12

1966255

To: Airport Manager, El Dorado Int'l Airport (SKBO), Bogota, Colombia


Info: FAA (AVP-1, AVP-200, AFS-280, AFS-200), A4A, AAAE, ALPA, APA, ASAP, ATSG, ICAO, ICASS, IFALPA, IPA, NBAA, NTSB

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: SKBO Runway 13L Charts and Markings

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 1966255

DATE / TIME

Date of Occurrence	202212
Local Time Of Day	1801 to 2400

PLACE

Locale	SKBO.Airport
State	FO

AIRCRAFT / EQUIPMENT X

Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

PERSON 1

Function - Flight Crew	Pilot Flying
ASRS Report Number	1966255

EVENTS

Anomaly	Ground Event / Encounter - Other / Unknown
Anomaly	No Specific Anomaly Occurred - Unwanted Situation
Detector - Person	Flight Crew
Result - General	None Reported / Taken

NARRATIVE 1

Departing Bogota Runway 13L. Holding short of Runway 13L noticed that the runway marking signs disagree with each other. The charts say 13L, the ground painted markings say 13L, yet the runway/taxiway sign says 14L. Just thought I would report the discrepancy in markings. Someone can check with Bogota Airport to determine why the Runway 13L markings while holding short are different.

SYNOPSIS

Air Carrier pilot reported the signage and charts do not agree for Runway 13L in SKBO, Bogota.