

7/21/2026

FOR YOUR INFORMATION

2026-258/11-49

To: Airport Manager, Bozeman Yellowstone Int'l Airport (BZN), MT, 2374014
FAA (AJV-A), Jeppesen Sanderson Inc.


Info: FAA (AAS-1, AAS-300, AVP-1, AVP-200, ATM BZN Tower, ANM-600, AFS-260, AFS-200, Director of Air Traffic Operations WSA), A4A, AAAE, ALPA, AOPA, APA, ASAP, CAPA, ATSAP, ATSG, IATA, IBT, ICAO, ICASS, IFALPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: BZN RNAV 12 Z Not Available in Jeppesen FD

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2374014**DATE / TIME**

Date of Occurrence	202606
Local Time Of Day	No Local Time Of Day Stated

PLACE

Locale	ZLC.ARTCC
State	UT

ENVIRONMENT

Flight Conditions	VMC
-------------------	-----

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Center	ZLC
Make Model Name	Large Transport, Low Wing, 2 Turbojet Eng
Operating Under FAR Part	121

COMPONENT 1

Aircraft Component	Electronic Flt Bag (EFB)
--------------------	--------------------------

PERSON 1

Function - Flight Crew	Captain
Function - Flight Crew	Pilot Not Flying
ASRS Report Number	2374014

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - Published
	Material / Policy
Detector - Person	Flight Crew
Result - Flight Crew	Overcame Equipment Problem

NARRATIVE 1

While at cruise from ZZZ-BZN, The FO (PF) made me aware she was going to setup for the RNAV 12 Z into BZN. When I went to change the approach in my JeppFD (Flight Deck) app, that approach wasn't available. We both verified we had the most up to date JeppFD with no updates required. I went through Mobile in Jeppesen trip kit to verify it was a legitimate legal approach for us. Once I found it, I downloaded it and used it for reference.

SYNOPSIS

Air carrier Captain reported JeppFD app did not have the BZN RNAV 12 Z available in the database.