

6/24/2026

FOR YOUR INFORMATION

2026-219/5-65

To: Airport Manager, Chicago O'Hare Int'l, (ORD), IL., FAA (AGL-600, ATM 2362561
ORD Tower, AJV-A), Jeppesen Sanderson Inc.


Info: FAA (Director of Air Traffic Operations CSA, AAS-1, AAS-300, AVP-1, AVP-200, AFS
-260, AFS-200, Runway Safety Team), A4A, AAAE, ALPA, AOPA, APA, ASAP,
ATSAP, ATSG, CAPA, IATA, ICASS, IFALPA, IPA, NATCA, NBAA, NTSB, RAA,
SWAPA

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: ORD Taxiway Charting

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2362561**DATE / TIME**

Date of Occurrence	202605
Local Time Of Day	No Local Time Of Day Stated

PLACE

Locale	ORD.Airport
State	IL
Altitude - AGL	0

ENVIRONMENT

Flight Conditions	VMC
-------------------	-----

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Ground	ORD
Make Model Name	Commercial Fixed Wing
Operating Under FAR Part	121

PERSON 1

Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Not Flying
ASRS Report Number	2362561

EVENTS

Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Flight Crew
Result - General	None Reported / Taken

NARRATIVE 1

The standard taxi route plates 20-6A and 20-6C incorrectly list Taxiway B as PP leading to confusion when referencing the plates.

SYNOPSIS

Air carrier First Officer reported the taxi route plates at ORD incorrectly list Taxiway B as PP.