11/13/2024

FOR YOUR INFORMATION

2024-207/5-71

2168444

To: Airport Manager, Washington Dulles International Airport (IAD), VA, FAA (AAS-1)

Info: FAA (Director of Air Traffic Operations ESA North, ATM IAD Tower, AAS-300, AVP-1, AVP-200, AEA-600, AFS-280, AFS-200, AJI-144, Runway Safety Team), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, ICASS, IFALPA, IPA, NATCA,

NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director

NASA Aviation Safety Reporting System

Re: IAD Airport Taxiway Line Visibility

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.





ACN 2168444	
DATE / TIME	
Date of Occurrence Local Time Of Day	202409 No Local Time Of Day Stated
PLACE	
Locale State Altitude - AGL	IAD.Airport DC 0
ENVIRONMENT	
Weather	Rain
AIRCRAFT / EQUIPMENT X	
ATC / Advisory - Ramp Make Model Name Operating Under FAR Part	IAD Commercial Fixed Wing 121
PERSON 1	
Function - Flight Crew ASRS Report Number	Captain 2168444
EVENTS	
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Anomaly Anomaly Detector - Person	Ground Event / Encounter - Ground Equipment Issue Ground Event / Encounter - Weather / Turbulence Flight Crew
NARRATIVE 1	

IAD Ramp area Taxiway Charlie and Taxiway Delta lines are obscured/difficult to see when wet/during rain at night. Also, lead-in line and gate centerline for D1 and other C/D gates at IAD obscured/difficult to see when wet/during rain at night.

SYNOPSIS

Air carrier Captain reported the IAD Ramp area, multiple taxiway lines, and the lead-in line and gate centerline for multiple gates are obscured and difficult to see when it is wet and/or during nighttime conditions.